

Hermes Shutdown Plans

Overview

Move Spectrometer	KW1 14.11-20.11
Remove Pol Target	KW1-2 14.11-23.11
Survey and prepare area	KW2 23.11-28.11
Remove Lambda wheels	KW3 28.11-04.12
Install and survey new vacuum chambers	KW4 05.12-11.12
Install Magnet	KW4 05.12-11.12
Install SFT and target	KW5 12.12-18.12
Install silicon detector	KW6 19.12-25.12

Prepare UGFS	KW7
Cable detector	26.11-01.01
Install Lambda wheels	KW8 02.01-08.01
Hermes to beam position	KW9 09.01-15.01
Survey detector	KW10 16.01-22.01
Test Detector	KW11 23.01-30.01