



Studies for Exp:
TSP Firing, e-beam gas Effect ?
Position & angle scan at IP
South,
energy scan protons

Machine Studies
Orbit Feedback,
Optic checks Hera-e

technical Problems:
Water leakage at BLM's,
208 MHz system "C" defect,
diodes at p-Colli WL19 repaired.

stable e+ beam stable e+

Luminosity Runs using 60 p-Bunches