


ZEUS 19 Apr 2005



Background history in
the week after BU SR
repair



TSP

p vacuum

TSP





Cursor: Sat Apr 16 12:2

- SR079
- SR065
- SR044
- SR092

- E-Energy
- E-Current
- P-Energy
- P-Current



Remove

Kino



before TSP regeneration





after TSP regeneration




before BU SR repair

good fill

bad fill



high dead time



HV efficiency and dead dtime is improving